

Date:

Spinelli Kia

4463 Boulevard des Sources Roxboro H8Y 3C1

1 581 703-8464

Make / Model	
Kia Seltos SX Turbo	
Year	Mileage indicated / actual*
2021	62,719 km
Transmission	Drive Type
automatic	AWD
Engine	Fuel Type
4 cyl. / 1.6 liters	unleaded
Serial number	Stock number
	K25178A



EQUIPMENTS

SALE PRICE

Adaptive cruise control, Air conditioning, Cruise control, Heated mirrors, Power Mirrors, Power driver seat, Power steering, Power windows, Remote starter, Adjustable steering wheel, Heated steering, Driver airbag, Passenger airbag, Rear defrost, Stability control, Traction control, Intermittent wipers, Rain sensor wipers, Two-toned paint, Satellite radio, Bucket seats, Head up display, Reverse camera, Variable speed intermittent wipers, Child safety locks, Climate control, Integrated turn signal mirrors, Driver vanity mirror, Passenger vanity mirror, Driver illuminated vanity mirror, Pass-Through rear seat, Power passenger seat, Rear head air bag, Anti-theft system, Brake assist, Auxiliary audio input, Keyless entry, Auto-on headlights, Keyless start, Remote trunk release, Audio steering controls

Plus tax.

Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for:

The dealer will supply upon request the name and phone number of the last owner.

	Category
Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a: Legal warranty: B - 3 month - 5000 KM	As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below: A 6 months or B 3 months or C 1 month or 1 700 km D Good working (subject to 37, 38 L.P.C.)
	(subject to 37, 36 E.P.C.) warranty
Repairs done and mechanical verification certificate Comments	
The following repairs have been done on this vehicle since th	e dealer's possession.
If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.	
Optional repairs	
The following defects have been noted on this vehicle and can be repaired at the cost mentioned below :	

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Signature :



Sticker #:

8469586